## Material safety data sheet

Section 1:Product Identification

IAFR Flooring Repair Adhesive

Manufacturer: Inject-A-Floor® Systems, Inc.,: TOLI FREE No. 800-769-8853

Ph: 407-304-4622 Fax: 407-304-4684.

Section 2: Incredents/Identity Information

Hazardous Components: No hazardous Ingredients or mixtures.

Section 3: Physical/Chemical Characteristics

Boiling point: 2120. Vapor Pressure (mmHg) 170-200C (Vapor Density Air=1); <1.

Solubility in Water: Soluble

Appearance and Odor: Milky-white ilquid; Mild Non-Irritating

Specific Gravity: 1.0-1.2. Melting Point: 50-54%

Evaporation Rate: <1 (Butyl Acetate+1)

Section 4: Fire and Explosion Hazard Date

Flash Point Method: Non-Combustible

Flammable Limits: N/A

Edinguishing Media: Water fog-dry reain only

Special Fire Fighting Procedures: As a resin, materials is not flammable. However the dried resin is

flammable similar to wood. Burning emits dense black smoke.

Unusual Fire and Explosion Hazards: Materiula can spatter above 100°C/212°F

Section 5: Reactivity Data

Stability: Stable. Conditions to Avoid: N/A

Incompatibility (Materials to Avoid): Addition of chemicals may cause coaquistion

Hazardous Decomposition or By Products: if burned produces a dense black smoke and noxique gases.

Hezerdous Polymerization: Condition to Avoid: N/A. Will not occur.

**Baction 6: Health Hazard Date** 

Primary Route(s) of Entity: Inhalation: Move to fresh air

Skin: Wash affected areas with soap and water

ingestion: Drink plenty of water

Health Hazards (Acute and Chronic): None known

Signs and Symptoms of Exposure: Possible mild irritation to the ayes.

Good hygienic practices should be followed.

Medical Conditions Generally Aggravated by Exposure: None known Emergency and First Aid Procedures: Flush with water for 5 minutes

Skin: Wash affected areas with soap and water

Inhalation: Move to fresh air

Section 7: Precentions For Safe Handling And Use

Steps to be taken in case materials is released or spilled: Keep apectators away. Floor may be slippery. Use care to avoid falling. Dike spill with sand, Transfer liquid to containers for disposal. Rinse down remaining materials with water before allowing to dry out. Waste disposal method: Coagulate liquid with addition of ferric chloride and lime. Landfill solids and diking materials according to local requiations. Precautions to be taken in handling and storing:

Keep from freezing. Store at temperatures between 40°F and 90°F.

Material may develop bacteria odor on long term storage.

Other Precautions: Spills may cause slippery surface. Product when dry is hard to remove.

Practice reasonable care to avoid repeated prolonged skin contact.

Section 8: Control Measures

Respiratory Protection: None required if good ventilation is maintained.

Local Exhaust: N/A Protective Gloves: Suggested, not mandatory. Eyes: Safety glasses.

Other Protective Cinthing or Equipment Not pageggry